




Series "DD" One-Side Strain Gauge



Compatible adhesive & Operational temperature
 CN: - 10~ + 70°C
 P-2: - 10~ + 70°C

Operational temperature -10~+70°C

ONE-SIDE STRAIN GAUGE										
Gauge pattern	Thickness of applicable specimen (mm)	Type	Gauge size		Backing			Resistance in Ω		
			L	W	L	W				
<p>This gauge can measure tensile strain and bending strain separately by simply bonding the gauge to one side of a plate or a beam.</p>  <p>Each package contains 5 gauges. Leadwire-integral service is available on request.</p>			L : length		W : width (Unit : mm)					
					a	b	c			
			Approx. 5 or less	DD-1-15			15		7	1
			Approx. 5~10	DD-2-30	3	2.9	30		7	2
		Approx. 10~15	DD-3-45			45	7	3		

LEADERS IN SENSORS & HEAVY DUTY JOYSTICKS

ALTHERIS bv

Scheveningseweg 15
 2517 KS DEN HAAG
 The Netherlands

+31 (0)70 3924421

+31 (0)70 3644249

Offices in : Benelux | Germany | France | UK | Italy | USA

www.altheris.com

sales@altheris.nl

